



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

February 1, 2006

Supervisor 10271

Mine Name:
Operator Name:

Permit number: M/029/004
Inspection Date: May 19, 2005
Time: 10:00 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Scott Rees, operator
Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This inspection was done to verify abatement work on violation issued May 2, 2005

Inspection Summary:

10. Abatement required all operations be confined to the previously accepted 5-acre small mining permit area, and that this area be marked so that it would be easily determined in the field. This inspection found that survey stakes with flagging had been placed to identify the SMO area. All operations appeared to be restricted to this area.

Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature LK

Date: February 1, 2006

LK:pb

O:\M029-Morgan\S0290004-RoundValley\inspection\insp-05192005.doc